

Shuna Street Glasgow

The former industrial site belonging to the McLellan rubber works required extensive remediation before it could be returned to community use. Following analysis of soil samples a system using bioremediation techniques was adopted to break down hydrocarbons resulting in 5,000 cubic metres of soil being successfully treated. Located on the edge of the Forth and Clyde canal, the development has created 176 homes comprising 1 and 2-bed apartments and 3 and 4-bed townhouses.

Case Study

Bellway